

3

On/off button - click
3 times to activate
all 3 LED lights

2

Light intensity
adjustment dial -
set in up position
(as shown) for
max illumination
strength

1

**Color coded
size indicator** -
push in until flush
with handle to
activate batteries



ONETRAC LX CONTROL GUIDE